

RESOLUTION #14-2016/2017

WHEREAS: The Grundy County Board of Supervisors is empowered under authority of Sections 321.236(8), 321.255, 321.471 to 321.473 of the Code of Iowa to impose weight limitations on highway structures under their jurisdiction and in accordance with the National Bridge Inspection Standards.

NOW THEREFORE BE IT RESOLVED by the Grundy County Board of Supervisors that vehicle and load limits be established and that signs be erected advising of the permissible maximum weights thereof on the bridges listed as follows:

- Bridge located near N 1/4 Corner, Sec. 18-89-16, Beaver Township, (#B-10) - New Posting Load - 22,37,38 Tons
- Bridge located near N 1/4 Corner, Sec. 36-89-16, Beaver Township, (#B-20) - New Posting Load - 9 Tons
- Bridge located near NW Corner, Sec. 6-89-17, Pleasant Valley Township, (#C-04) - New Posting Load - 21,33,36 Tons
- Bridge located near NW Corner, Sec. 15-89-17, Pleasant Valley Township, (#C-11) - New Posting Load - "One Truck on Bridge" series
- Bridge located near NW Corner, Sec. 28-89-17, Pleasant Valley Township, (#C-26) - New Posting Load - 10 Tons
- Bridge located near W 1/4 Corner, Sec. 31-89-17, Pleasant Valley Township, (#C-30) - New Posting Load - 10 Tons
- Bridge located near N 1/4 Corner, Sec. 33-89-17, Pleasant Valley Township, (#C-31) - New Posting Load - 3 Tons
- Bridge located near N 1/4 Corner, Sec. 10-89-18, German Township, (#D-10) - New Posting Load - 12,21,22 Tons
- Bridge located near SW Corner, Sec. 8-88-18, Shiloh Township, (#E-08) - New Posting Load - 6 Tons
- Bridge located near N1/4 Corner, Sec. 6-88-17, Colfax Township, (#F-04) - New Posting Load - 8 Tons
- Bridge located near NW Corner, Sec. 16-88-16, Lincoln Township, (#G-10) - New Posting Load - 18,29,32 Tons
- Bridge located near SW Corner, Sec. 19-87-17, Palermo Township, (#K-09) - New Posting Load - 12 Tons
- Bridge located near W1/4 Corner, Sec. 35-87-17, Palermo Township, (#K-12) - New Posting Load - 6 Tons
- Bridge located near SW Corner, Sec. 34-87-18, Melrose Township, (#L-19) - New Posting Load - 21,32,32 Tons
- Bridge located near NW1/4 Corner, Sec. 6-86-18, Felix Township, (#M-05) - New Posting Load - 16,26,30 Tons
- Bridge located near W1/4 Corner, Sec. 20-86-18, Felix Township, (#M-17) - New Posting Load - 25,30,30 Tons
- Bridge located near N1/4 Corner, Sec. 12-86-17, Clay Township, (#N-09) - New Posting Load - 25,33,34 Ton
- Bridge located near NE Corner, Sec. 18-86-17, Clay Township, (#N-12) - New Posting Load - 17,26,30Ton

BE IT FURTHER RESOLVED that all resolutions or parts of resolutions in conflict with the provisions of this resolution are hereby repealed.

Passed and Approved this 6th day of September, 2016.

Barbara J. Smith
Barbara L. Smith, Chairperson
Grundy County Board of Supervisors

ATTEST:
Rhonda R. Deters
Rhonda R. Deters, Grundy County Auditor
Bridge Load Limit 2016_Sept.doc